

Long handled pliers
Oxy-acetylene welders goggles (purchase at Arcet)
Leather work gloves

Please wear heavy pants, sturdy shoes or boots, a long sleeved shirt, and hat if desired to protect your hair or scalp.